



# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, September 24, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread H: Montgomery County	Pipe Yard 006	Site Conditions:	Rainy

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Rough Grading      ☐ Trenching      ☐ Stringing/Welding
- ☐ Lowering/Backfilling      ☐ Final Grading      ☐ Temp. Stabilization      ☐ Perm. Stabilization      ☒ Other

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

Corrective Action: N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Tuesday, September 24, 2024

# STANDARDS & SPECIFICATIONS

## SITE INSPECTION REPORT

### LEVEL 1 (FIELD REPORT)

### FIELD INSPECTION PHOTO LOG

Fig. 1  
**PY-006:** Controls in place and functioning properly.



Fig. 2  
**PY-006:** Controls in place and functioning properly.



Fig. 3  
**PY-006:** Controls in place and functioning properly.




Fig. 4  
**PY-006:** Controls in place and functioning properly.

