



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Monday, March 31, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread I: Franklin County	STA 13437+00 – 13496+00 MVP-FR-293.02	Site Conditions:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
- ☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☒ Perm. Stabilization ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ8.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13440+00 to 13444+00: Repair erosion and restabilize denuded areas.
- STA 13450+00 to 13451+00: Repair erosion and restabilize denuded areas.


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Monday, March 31, 2025

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13440+00 to 13444+00: Repair and restabilize denuded areas.



Fig. 2

STA 13440+00 to 13444+00: Repair and restabilize denuded areas.



Fig. 3

STA 13450+00 to 13451+00: Repair and restabilize denuded areas.



Fig. 4

STA 12423+00: Controls in place and functioning properly.

