

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Tuesday, April 15, 2025			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com			
Spread H: Roanoke County Franklin County	STA 12742+00 - 12750+00 STA 12760+00 - 12763+00 STA 13258+00 - 13270+00 STA 13185+00 - 13195+00 MVP-RO-281/281.02 MVP-FR-293.01/292.01	Site Conditions:	Wet			

<u>ACTI</u>	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)														
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		☐ Trenching		Stri	nging/Weldin				
	Lowering/Backfilling			Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	on 🗵 BMF		P Installation				
									Yes	No	N/A				
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?														
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?									$\boxtimes$					
	3. Areas of offsite sediment deposition observed?									$\boxtimes$					
		e Maintena	ınce:	he following resource ( <u>72-Hour Deadline</u> fro to 12775+50: Restal	om Noti		, S-EF	-736 and S-II4.							
	Ineffective Controls: ( <u>24-Hour Deadline</u> from Notification) - N/A														
	Corre	ctive Actio	<u>on:</u> N	Maintain and install	all con	trols per the approve	ed S&	S.							

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, April 15, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1 STA 12775+00 to 12775+50: Restabilize permanent waterbars.



Fig. 2 **Stream S-EF34B:** Controls in place and functioning properly.



Fig. 3 **STA 12775+00:** Controls in place and functioning properly.



Fig. 4
STA 12746+00: Controls in place and functioning properly.

