

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Wednesday, May 14, 2025			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com			
Spread H: Roanoke County Franklin County	STA 13410+00 - 13415+51 STA 13337+13 - 13348+46 STA 12760+00 - 12776+00 MVP-RO-282	Site Conditions:	Rainy			

CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
Tree Felling			☐ Clearing/Grubbing		☐ Rough Grading		☐ Trenching		Str	inging/Welding			
Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗆	Other				
								Yes	No	N/A			
1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						\boxtimes						
2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						\boxtimes						
3.	Areas of offsite sediment deposition observed?							\boxtimes					
Routin - Ineffec	ne Maintena N/A ctive Contro N/A	nce: ols:	-	s: S-IJ1	1, S-IJ2, S-IJ3, W-IJ2, \$	S-RRO	08, S-GH9, S-EF32	and S-E	EF36.				
	1. 2. 3. Comm Routing-	1. Are control sediment of sed	Tree Felling Lowering/Backfilling 1. Are controls instance sediment control months and sediment control months are all control months and sediment control months. Inspected to Routine Maintenance: - N/A Ineffective Controls: - N/A	Tree Felling Clearing/Grubbing Lowering/Backfilling Final Grading 1. Are controls installed and implemente sediment control plan and stormwater 2. Are all control measures properly main with good engineering practices and, and a stormwater of the sediment deposition d	Tree Felling Clearing/Grubbing Lowering/Backfilling Final Grading 1. Are controls installed and implemented in acceptable sediment control plan and stormwater managed. 2. Are all control measures properly maintained with good engineering practices and, where 3. Areas of offsite sediment deposition observed. Comments: Inspected the following resources: S-IJ Areas of Maintenance: N/A Ineffective Controls: N/A	Tree Felling	Tree Felling	Tree Felling	Tree Felling	Tree Felling			

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, May 14, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 13415+00:** Controls in place and functioning properly.



Fig. 2 **STA 13342+00:** Controls in place and functioning properly.



Fig. 3

Stream S-IJ1: Controls in place and functioning properly.



Fig. 4
STA 12776+00: Controls in place and functioning properly.

