



# STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Matthew Grant	Inspection Date:	Wednesday, June 4, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread H: Montgomery County	STA 12315-12430 MN279	Site Conditions:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Rough Grading      ☐ Trenching      ☐ Stringing/Welding
- ☐ Lowering/Backfilling      ☐ Final Grading      ☐ Temp. Stabilization      ☒ Perm. Stabilization      ☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-NN19, S-0016

**Routine Maintenance:** (72-Hour Deadline from Notification)

- STA 12315: Repair ECM

**Ineffective Controls:** (24-Hour Deadline from Notification)

- N/A

**Corrective Action:** Maintain and install all controls per the approved S&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

**Date:** Wednesday, June 4, 2025

# STANDARDS & SPECIFICATIONS

## SITE INSPECTION REPORT

### LEVEL 1 (FIELD REPORT)

### FIELD INSPECTION PHOTO LOG

Fig. 1

**STA 12315: Repair ECM**



Fig. 2

**Designated Crossing S-0016: ECD's remain in place.**



Fig. 3

**Designated Crossing S-NN19: ECD's remain in place.**



Fig. 4

**STA 12409: Access road and stabilization remain in place.**

