



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector: M. Willis	Matthew Grant	Inspection Date:	Tuesday, June 24, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread G: Giles County	STA 10529-10600 GI 235 ATWS 1124, 1125, 1126, 1127, 1128, 1132 MLV 23	Site Conditions:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
- ☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☒ Perm. Stabilization ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-S5

Routine Maintenance: (72-Hour Deadline from Notification)

- STA10580-10580+50: repair and restabilize area
- STA 10585+38: repair and restabilize area

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Tuesday, June 24, 2025

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 10580: repair and restabilize.



Fig. 2

STA 10590: ECD's remain in place.



Fig. 3

STA 10585+38: repair and restabilize area.



Fig. 4

STA 10535: ECD's remain in place.

