

Tuesday, July 29, 2025

Date:

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, July 29, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Pittslyvania County	STA 15370+62 - 15390+00 STA 15584+23 - 15619+48	Site Conditions:	Dry

<u>ACT</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	g		Clearing/Grubbing		Rough Grading		Trenching		Strin	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	□ Perm. Stabilization			Othe	er			
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes					
	3.	3. Areas of offsite sediment deposition observed?								\boxtimes				
	Comments: Inspected the following resources: W-MM9, D-G6, S-CC1, W-MM8, S-CC3 and S-P5. Routine Maintenance (72-Hr): - N/A Ineffective Controls (24-Hr): - N/A Corrective Action: N/A													
The reconst	ector Sign	corrective ac pliance and/c e on the abo	or corr	ective actions are not con	condit	ions noted on this report u l by the deadline, other enf	nless forcem	otherwise noted. If liste nent actions may be iss	d condi ued to t	tion(s) (he entit	currently y responsible for			



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 STA 15380+00: Controls removed.



Fig. 2 **STA 15594+00:** Controls in place and functioning properly.



Fig. 3 **STA 15592+00:** Controls in place and functioning properly.



Fig. 4
STA 15618+00: Landowner has resumed Agricultural activity.

