

Tuesday, August 19, 2025

Date:

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, August 19, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread H: Franklin County	STA 13342+67 - 13415+51 MVP-MLV-AR-29	Site Conditions:	Dry

<u>ACT</u>	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Fellin	g		Clearing/Grubbing		Rough Grading		Trenching		Strir	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	□ Perm. Stabilizatio			Othe	er			
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes					
	2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
	3.	3. Areas of offsite sediment deposition observed?								\boxtimes				
	Comments: Inspected the following resources: S-RR08, S-RR09, S-RR11, S-IJ1, S-IJ2, W-IJ1, W-IJ2 and S-IJ3. Routine Maintenance (72-Hr): - N/A Ineffective Controls (24-Hr): - N/A Corrective Action: N/A													
The reconst		corrective ac pliance and/c e on the abo	or corre	ective actions are not cor		ions noted on this report u by the deadline, other ent								



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13416+00: Controls in place and functioning properly.



Fig. 2 **STA 13399+00:** Controls in place and functioning properly.



Fig. 3 STA 13359+00: ECDs removed. Trash placed into supersacks for future removal.



Fig. 4

STA 13344+00: ECDs removed. Trash placed into supersacks for future removal.

