

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, September 22, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14018+47 – 140342+25 ATWS 1470/1471	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling      ☐ Clearing/Grubbing      ☐ Grading      ☐ Trenching      ☐ Stringing/Welding  
☐ Lowering/Backfilling      ☐ Final Restoration      ☐ Temp. Stabilization      ☐ Perm. Stabilization      ☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-KL39.

**Routine Maintenance:** *(72-Hour Deadline from Notification)*

- STA 14021 to 14032: Re-stabilization needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Tuesday, September 22, 2020

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, September 22, 2020

**Figure 1: STA 14026+00 – Re-stabilization needed.**



**Figure 2: STA 14021+00 – Re-stabilization needed.**



**Figure 3: STA 14030+00 – Re-stabilization needed.**



**Figure 4: Stream S-KL39 – Controls in place and functioning properly around S-KL39 crossing.**

