

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, February 23, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 15465+00 – 15508+00 STA 14860, 14756, 14698	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|---|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☒ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, February 23, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 23, 2021

Figure 1: STA 14863+00 – Controls in place and functioning properly. Area recently stabilized with Earth-Guard Edge.

BRG: 127°SE (T) **LAT:** 36.971454 **LON:** -79.659382 ±16ft **ALT:** 974ft



Figure 2: STA 14761+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 302°NW (T) **LAT:** 36.984131 **LON:** -79.690359 ±16ft **ALT:** 921ft



Figure 3: STA 14756+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 124°SE (T) **LAT:** 36.983305 **LON:** -79.689582 ±16ft **ALT:** 942ft



Figure 4: STA 14698+00 – Controls in place and functioning properly. Area stabilized with straw.

BRG: 81°E (T) **LAT:** 36.988536 **LON:** -79.708993 ±98ft **ALT:** 925ft

