

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, February 22, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County Roanoke County	MVP-FR-291/290/289/288 MVP-RO-281	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-KL41, W-RR4, S-RR6, S-RR18, W-RR3, S-G26, S-G27, W-Q11, S-KL4 and S-EF32.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Monday, February 22, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, February 22, 2021

Figure 1: MVP-FR-291 – Controls in place and functioning properly.

BRG: 170°S (T) **LAT:** 37.115510 **LON:** -80.099121 ±213ft **ALT:** 2629ft



Figure 2: MVP-FR-290 – Controls in place and functioning properly.

BRG: 195°S (T) **LAT:** 37.125257 **LON:** -80.113652 ±98ft **ALT:** 2600ft



Figure 3: Wetland W-Q11 – Controls in place and functioning properly around wetland W-Q11 along MVP-FR-288.

BRG: 248°SW (T) **LAT:** 37.132396 **LON:** -80.131315 ±16ft **ALT:** 2617ft



Figure 4: MVP-RO-281 – Controls in place and functioning properly.

BRG: 248°W (T) **LAT:** 37.182071 **LON:** -80.145599 ±16ft **ALT:** 3011ft

