

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 3, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13823+00 – 13892+45 MVP-FR-302	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C14, S-C16, S-C17, W-CD6, S-CD6 and W-CD5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, February 3, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 3, 2021

Figure 1: STA 13831+00 – Controls in place and functioning properly.

BRG: 162°S (T) **LAT:** 37.064111 **LON:** -79.922933 ±541ft **ALT:** 1113ft



Figure 2: STA 13856+00 – Controls in place and functioning properly.

BRG: 107°E (T) **LAT:** 37.058547 **LON:** -79.919452 ±98ft **ALT:** 1157ft



Figure 3: STA 13863+00 – Controls in place and functioning properly.

BRG: 110°E (T) **LAT:** 37.058347 **LON:** -79.917706 ±16ft **ALT:** 1054ft



Figure 4: Wetland W-CD5 – Controls in place and functioning properly.

BRG: 163°S (T) **LAT:** 37.067180 **LON:** -79.899833 ±8373ft **ALT:** 1033ft

