

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 28, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	H-601 Line H-602 Line Transco-Interconnect MVP-PI-343	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H42.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, January 28, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 28, 2021

Figure 1: H-603 Line – Controls in place and functioning properly.

BRG: 213°SW (T) **LAT:** 36.834861 **LON:** -79.342099 ±213ft **ALT:** 677ft



Figure 2: STA 16022+00 – Controls in place and functioning properly.

BRG: 231°SW (T) **LAT:** 36.831238 **LON:** -79.343074 ±8996ft **ALT:** 622ft



Figure 3: H-602 Line – Controls in place and functioning properly.

BRG: 247°SW (T) **LAT:** 36.830390 **LON:** -79.343817 ±98ft **ALT:** 636ft



Figure 4: Stream S-H42 – Controls in place and functioning properly.

BRG: 227°SW (T) **LAT:** 36.829104 **LON:** -79.344447 ±16ft **ALT:** 635ft

