

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, June 23, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12373+28 – 12434+00 MVP-MN-279/279.02 ATWS 1506/1507/726/725	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-OO16, S-NN19 and S-NN16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, June 23, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 23, 2020

Figure 1: MVP-MN-279 – Controls in place and functioning properly.

☼ 274°W (T) ● 37°14'7"N, 80°11'42"W ±16ft ▲ 1182ft



Figure 2: STA 12418+00 – Controls in place and functioning properly. Area stabilized.

☼ 197°S (T) ● 37°14'16"N, 80°11'57"W ±98ft ▲ 1093ft



Figure 3: STA 12410+00 – Controls in place and functioning properly. Area stabilized.

☼ 308°NW (T) ● 37°14'22"N, 80°11'57"W ±16ft ▲ 1390ft



Figure 4: STA 12385+00 – Controls in place and functioning properly. Area stabilized.

☼ 294°NW (T) ● 37°14'36"N, 80°12'20"W ±98ft ▲ 1404ft

