

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 22, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County Pittsylvania County	STA 15210+56 – 15260+00 STA 14802+19 – 14816+07 MVP-FR-323/MVP-PI-328 ATWS 488/1522/1523/1282	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-H23 and S-HH1.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 1/22/2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 22, 2020

Fig. 1: **STA 15214+00** – Controls in place and functioning properly. Area stabilized with vegetation.

☼ 109°E (T) ● 36°56'23"N, 79°33'28"W ±32.8ft ▲ 841ft



Fig. 2: **STA 15223+00** – Controls in place and functioning properly. Area stabilized with vegetation.

☼ 111°E (T) ● 36°56'19"N, 79°33'17"W ±16.4ft ▲ 821ft



Fig. 3: **STA 14802+00** – Controls in place and functioning properly. Area stabilized with vegetation and Earth Guard.

☼ 133°SE (T) ● 36°58'36"N, 79°40'41"W ±16.4ft ▲ 948ft



Fig. 4: **Stream S-HH1** – Controls in place and functioning properly. Area stabilized with vegetation.

☼ 347°N (T) ● 36°58'29"N, 79°40'28"W ±16.4ft ▲ 903ft

