

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 10, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14411+04 – 14524+76 MVP-FR-317 ATWS 358/358A/527/359/1340/360	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GH36, S-KL17, S-GH37, S-GH38, S-GH37, S-GH39, S-G22, S-G23, S-G21 and S-G20.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 1/10/2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 10, 2020

Fig. 1: **STA 14414+00** – Controls in place and functioning properly.



Fig. 2: **Wetland W-GH16** – Controls in place and functioning properly.



Fig. 3: **STA 14460+00** – Controls in place and functioning properly.



Fig. 4: **STA 14480+50** – Controls in place and functioning properly around Stream S-G22.

