

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, January 9, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14311+57 – 14411+04 MVP-FR-313.01/314/315 ATWS 1485/526/526A/622/623/356	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-GG4, S-A36, S-A38, S-A40, W-DD1, S-A41 and W-A12-PFO.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 1/9/2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 9, 2020

Fig. 1: **STA 14328+00** – Controls in place and functioning properly. Area stabilized with Earth Guard.

☼ 331°NW (T) ● 37°2'25"N, 79°48'21"W ±10184.2ft ▲ 1163ft



Fig. 2: **STA 14334+00** – Controls in place and functioning properly. Area stabilized with Earth Guard.

☼ 153°SE (T) ● 37°2'18"N, 79°48'22"W ±541.4ft ▲ 1175ft



Fig. 3: **Stream S-A38** – Controls in place and functioning properly at Stream S-A38/S-A40.

☼ 95°E (T) ● 37°2'10"N, 79°47'58"W ±98.4ft ▲ 1071ft



Fig. 4: **STA 14400+00** – Controls in place and functioning properly. Area stabilized with Earth Guard.

☼ 287°W (T) ● 37°1'52"N, 79°47'5"W ±32.8ft ▲ 1055ft

