

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, February 6, 2020	Project Contact:	Brian Clauto,
Spread H: Montgomery	MP 231.04-230.8 ATWS 703, 704A, 1375, 1446 AR MN 274 & MN 275	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

- Comments: Inspected the following resources: S-C21, S-001
- ECD's were in place and functioning at the designated crossings.
- During the inspection, the railway ditch was releasing turbid water at the juncture of designated stream S-001 and S-C21.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A

Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Thursday, February 6, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 6, 2020

Figure 1: Off AR MN274 at the railway ditch crossing, turbid water is being released into S-C21. North Elevation 185°S (T) 37°15'6"N, 80°15'27"W ±16ft ▲ 1299ft 	Figure 2: At designated crossing S-C21, ECD's were in place. East Elevation 283°W (T) 37°15'7"N, 80°15'31"W ±16ft ▲ 1276ft 
Figure 3: Designated stream S-001 before railroad ditch crossing. South West Elevation 59°NE (T) 37°15'6"N, 80°15'25"W ±16ft ▲ 1313ft 	Figure 4: Near the railroad ditch and confluence of S-001, ECD's were in place. South Elevation 445°N (T) 37°15'6"N, 80°15'26"W ±16ft ▲ 1310ft 