

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, February 5, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County Roanoke County Franklin County	STA 12690+43 – 12713+62 MVP-FR-290/RO-280 STA 12435+96 – 12443+12 ATWS 1038/1225/1224/727	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S- RR17, W-RR4, W-RR3, S-RR16, W-KL41 and S-NN16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, February 5, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, February 5, 2020

Figure 1: MVP-FR-290 – Controls in place and functioning properly around Stream S-RR16 and W-RR3.



Figure 2: STA 12703+00 – Controls in place and functioning properly. Area stabilized with vegetation and erosion matting.



Figure 3: Stream S-NN16 – Controls in place and functioning properly around the Roanoke River.



Figure 4: ATWS 727 – Controls in place and functioning properly. Area stabilized with vegetation.

