

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, August 14, 2018	Project Contact:	Brian Clauto
Spread: Locations in Spread H inspected MP 246.5- 246.9	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☒ Clearing
 ☒ Rough Grading
 ☐ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization


☐ Other: _____

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:
Area 1 - Spread H, controls observed in place were functioning.

Deadline: _____ N/A _____

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____ Date 8-20-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 14, 2018

Fig. 1
Near station 13026+00, water bar and stabilization matting installed



Fig. 2
Near station 13017+55 water bar and slope stabilization applied



Fig. 3

Fig. 4