

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, December 20, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15693+89 – 15826+77 MVP-PI-337/338 ATWS 399/399A/631/499	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-B6, S-B8, S-B9, S-C1, S-KL27 and S-DD4.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/20/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, December 20, 2019

Fig. 1: **Stream S-B6** – Controls in place and properly functioning. Area stabilized with Earth-Guard.



Fig. 2: **STA 15810+00** – Controls in place and properly functioning. Area stabilized.



Fig. 3: **STA 15795+00** – Controls in place and properly functioning at Stream S-C1. Area stabilized.



Fig. 4: **STA 15762+00** – Controls in place and properly functioning. Area stabilized with vegetation.

