

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, December 19, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 12994+00 – 13042+58 STA 13251+29 – 13267+40 STA 13316+13 – 13295+82	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G24, W-ST2-PEM, S-H1, S-II4 and S-GH7.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 12/19/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 19, 2019

Fig. 1: **STA 12996+61** – Controls in place and properly functioning at the Blue Ridge Parkway.

☼ 289°W (T) ● 37°7'41"N, 80°7'42"W ±32.8ft ▲ 2711ft



Fig. 2: **STA 13260+00** – Controls in place and functioning properly. Area stabilized.

☼ 261°W (T) ● 37°3'53"N, 79°57'37"W ±19502.3ft ▲ 2639ft



Fig. 3: **Stream S-GH7** – Controls in place and functioning at Stream S-GH7.

☼ 299°NW (T) ● 37°6'23"N, 80°3'15"W ±16.4ft ▲ 1377ft



Fig. 4: **STA 13306+16** – Controls in place and properly functioning. Area stabilized.

☼ 344°N (T) ● 37°6'24"N, 80°3'18"W ±16.4ft ▲ 1384ft

