

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, December 10, 2019	Project Contact:	Brian Clauto
Spread: Roanoke Co. MP 245.9-245.3 AR RO-288 ATWS1307 & 1308 Montgomery Co. MP 230.6-230.7 AR MN 274 ATWS 704A, 1446,1062, 1375	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: W-KL 1, W-Q11, W-IJ 10, S-Q20, S-C21, S-0011
- As previously documented road gravel remains in W-Q11, no landowner approval for removal has been granted.
- All controls were in place and functioning at designated stream crossings and wetlands.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 12-30-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, December 10, 2019

- Fig. 1. Designated wetland W-Q11, road gravel has washed into wetlands.



- Fig. 2. Designated stream crossing S-C21, ECD's are in place and functioning.



- Fig. 3. Near designated stream S-0011 and intersection of railroad ditch line. ECD's and stabilization of ROW are in place and functioning.



- Fig. 4. Near St122200+22 above designated stream S-0011, stabilization and ECD's are functioning.

