

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, December 9, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13440+00 STA 13539+14 – 13542+58 STA 13562+63 – 13575+21 STA 13996+56 – 14001+97	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ4, S-KL36 and S-II7.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 12/09/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, December 9, 2019

Fig. 1: **STA 13438+31** – Controls in place and properly functioning. Area stabilized with vegetation.

☉ 135°SE (T) ☉ 37°5'24"N, 80°1'11"W ±16.4ft ▲ 1700ft



Fig. 2: **STA 13542+58** – Controls in place and functioning properly. Area stabilized with vegetation.

☉ 73°E (T) ☉ 37°5'28"N, 79°59'27"W ±16.4ft ▲ 1323ft



Fig. 3: **Stream S-II7** – Controls in place and functioning above Stream S-II7. Area stabilized with vegetation.

☉ 276°W (T) ☉ 37°5'28"N, 79°59'29"W ±16.4ft ▲ 1308ft



Fig. 4: **Stream S-KL36** – Controls in place and properly functioning along Stream S-KL36 crossing.

☉ 32°NE (T) ☉ 37°3'11"N, 79°53'4"W ±16.4ft ▲ 991ft

