

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, November 4, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13061+44 – 13116+87 MVP-FR-290/291	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G26, S-G27, S-RR16, S-RR18 and S-EF17.

Recommended Corrective Action: N/A.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 11/04/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, November 4, 2019

Fig. 1: **STA 13113+00** – Area at final restoration. Controls in place and functioning properly. Area stabilized with Proganics and flexterra.

☉ 327°NW (T) ☉ 37°7'20"N, 80°5'47"W ±98.4ft ▲ 2705ft



Fig. 2: **STA 13107+00** – Controls in place and functioning properly. Area stabilized with Proganics and flexterra.

☉ 301°NW (T) ☉ 37°7'24"N, 80°5'53"W ±98.4ft ▲ 2795ft



Fig. 3: **STA 13093+00** – Controls in place and functioning properly. Area stabilized with Proganics and flexterra.

☉ 246°SW (T) ☉ 37°7'30"N, 80°6'2"W ±32.8ft ▲ 2987ft



Fig. 4: **STA 13068+00** – Controls in place and functioning properly. Area stabilized with Proganics and flexterra.

☉ 112°E (T) ☉ 37°7'35"N, 80°6'33"W ±16.4ft ▲ 2679ft

