

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, October 22, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12179+00 – 12200+00 STA 12116+35 – 12120+34 MVP-MN-271/270.01/274 STA 12435+16 – 12437+00	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-C21, S-OO11, S-F16a/b, S-EF31, S-MM11 and S-NN16.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 10/22/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 22, 2019

Fig. 1: **STA 12190+00** – Controls in place along Bradshaw Road. Area stabilized with erosion matting, hydro-mulch and straw.

☉ 86°E (T) ☉ 37°15'6"N, 80°15'35"W ±16.4ft ▲ 1290ft



Fig. 2: **STA 12180+00** – Controls in place. Area stabilized with hydro-mulch.

☉ 352°N (T) ☉ 37°15'11"N, 80°15'44"W ±32.8ft ▲ 1408ft



Fig. 3: **STA 12117+62** – Controls in place. Area stabilized.

☉ 300°NW (T) ☉ 37°15'26"N, 80°16'57"W ±16.4ft ▲ 1443ft



Fig. 4: **STA 12436+35** – Controls in place. Area stabilized.

☉ 239°SW (T) ☉ 37°13'59"N, 80°11'53"W ±16.4ft ▲ 1203ft

