

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, August 28, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12703+08 – 12715+31 STA 13415+51 – 13342+67	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☒ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-RR11, S-RR09, S-RR08, S-IJ1, and S-IJ3.

STA 13374+00: Maintain P1.
 STA 13374+00: Maintain SSF.
 STA 13374+00: Stabilize slope.
 STA 13343+00: Clean up/remove trash.

Recommended Corrective Action: Install and maintain all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 08/28/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, August 28, 2019

Fig. 1: **STA 13374+00** – P1 undermined, maintenance needed.



Fig. 2: **STA 13374+00** – SSF maintenance needed.



Fig. 3: **STA 13374+00** – Repair and stabilize slope.



Fig. 4: **STA 13343+00** – Clean up/remove personal trash and waste.

