

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 12, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Storm preparation


- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- **Area 1** - MP 246.54 station#13013+20 - 13017+55 tie in crews working on this section of pipe and lowering / backfilling in this area, dewatering structure in place.
- **Area 2**- In the area of MP 252.21 St#13317+00 – 13320+00 blanket matting has been installed

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 9-17-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 12, 2018

Fig. 1
MP 246.47 St#13014+00 dewatering structure in place



Fig. 2
MP 246.46 St#13013+35 portions of pipe have been lowered.



Fig. 3
In the area of MP246.43 St# 13012+00 area has been matted.



Fig. 4
MP 252.21 St#13317+00 – 13320+00 blanket matting has been installed.

