

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, September 11, 2018	Project Contact:	Brian Clauto
Spread: Areas 1-4 Giles County & Area 5 Montgomery County	Spread G	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Storm prep

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments / Observations:

- **Area 1** - Access road G-I 234 conveyance channel completed
- **Area 2** - MP 206 bridge removed at designated stream SA-32
- **Area 3** - MP 207 bridge removed at designated stream SY3
- **Area 4** - MP 217 St#11472+00, karsts areas protected with triple stack, P1 & SSF.
- **Area 5** - MP 219.6 designated stream S-006, timber mats removed.

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 9-17-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, September 11, 2018

Fig. 1
Access road G-I 234 conveyance channel completed



Fig. 2
MP 206 bridge removed at designated stream SA-32



Fig. 3
MP 207 bridge removed at designated stream SY3



Fig. 4
MP 217 St#11472+00, karsts areas protected with triple stack, P1 & SSF.

