

## FIELD INSPECTION

|                  |                          |                         |               |
|------------------|--------------------------|-------------------------|---------------|
| Project Name:    | Mountain Valley Pipeline | Inspector:              | Matthew Grant |
| Inspection Date: | August 22 & 23, 2018     | Project Contact:        | Brian Clauto  |
| Spread:          | Spread H                 | Weather (Wet/Dry/Rain): | Dry           |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☒ Clearing
 ☒ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation  
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other: \_\_\_\_\_

- |                                                                                                                                                                                   | Yes                                 | No                                  | N/A                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Comments:**

- **Area 1** - Spread H, Montgomery County, near Reese Mountain Road, approximately MP 232 station 12285+75 to approximately MP 232.6 blanket matting had been installed.
- **Area 2**- Spread H, Franklin County, near Webster Corner Rd, approximately MP 253.1 station 13366+34 on going waterbar install construction and stabilization.
- **Area 3**- Spread H, Montgomery County, approximately MP 227.7 designated stream S-G36 crossing stabilization in place.

**Deadline:**   N/A  

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date:   9-4-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, August 23, 2018

Fig. 1  
Near St# 12285+75 blanket matting installed



Fig. 2  
Near St# 13366+34 waterbar install



Fig. 3  
S-G36 crossing re contoured per the approved plan



Fig. 4