

FIELD INSPECTION

| | | | |
|---|--------------------------|--------------------------------|---------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Matthew Grant |
| Inspection Date: | Tuesday, August 13, 2019 | Project Contact: | Cory Chalmers |
| Spread: Montgomery County MP236 St12470-12482+67 | Spread H | Weather (Wet/Dry/Rain): | Dry |

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated wetland included: WKL 58, ECD's were in place and functioning.
- ECD's in this section of ROW are in place and functioning, stabilization has been applied as well.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 8-19-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, August 13, 2019

- Fig. 1 Designated wetland WKL58, ECD's are in place and functioning.

East Elevation

☉ 280°W (T) ☉ 37°14'18"N, 80°13'17"W ±9482.1ft ▲ 1256ft



- Fig. 2 Near St12470+00 stabilization has been applied.

North West Elevation

☉ 138°SE (T) ☉ 37°13'40"N, 80°12'11"W ±16.4ft ▲ 1232ft



- Fig. 3. Near St12181+00 ECD's are in place and stabilization has been applied.

North Elevation

☉ 160°S (T) ☉ 37°13'35"N, 80°12'8"W ±16.4ft ▲ 1353ft



- Fig. 4. Near St12482+67 stabilization has been applied.

South Elevation

☉ 342°N (T) ☉ 37°13'31"N, 80°12'14"W ±3192.4ft ▲ 1548ft

