

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, July 9, 2019	Project Contact:	Brian Clauto
Spread H: Montgomery County	STA 12072+00 – 12191+00 MVP-MN-270	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-F15, S-F16A/B, S-C36, S-MM31, S-C29, W-C6, W-C5, S-C25 and S-C24.

- STA 12112+63: SSF needs maintenance.
- STA 12117+00: Bridge sideboards need maintenance.
- STA 12143+59: Bridge "waddles" need maintenance.
- STA 12163+05: CFS needs maintenance.
- STA 12163+05: Bridge "waddles" need maintenance.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 07/09/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 9, 2019

Fig. 1: **STA 12112+00** – SSF in need of maintenance.



Fig. 2: **STA 12117+00** – Bridge sideboards in need of maintenance.



Fig. 3: **STA 12143+59** – CFS "Waddles" need maintenance at wetland W-C5.



Fig. 4: **STA 12163+05** – CFS needs maintenance at stream S-C25.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, July 9, 2019

Fig. 5: **STA 12163+05** – CFS “Waddles” need maintenance at stream S-C25.

