

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, June 25, 2019	Project Contact:	Brian Clauto
Spread: Roanoke County AR 288 Franklin County MP247 St13067 MP 276 St12282	Spread H	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☒ Clearing
☐ Rough Grading
☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration
☐ Final Grading & Stabilization

☒ Other: bore sites & dormant areas

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: W—IJ10, W-K11, W-Q11, S-Q20, S-G26, S-G27,
- ECD devices were installed as well as dewatering devices at bore site.
- Areas of road stone were offsite as noted on 6-11-19 report, currently waiting on land owner approval to remove stone.
- At the time of inspection, tree removal was being conducted at Reese Mountain.
- At AR 276.03 ECD requires repair.

Recommended Corrective Action: Remove offsite stone per DEQ approval, maintain all controls per the approved plan.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 7/22/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 25, 2019

- Fig. 1 ECD controls are in place at the bore pit for designated streams S-G26 & S-G27



- Fig. 2 ECD controls are in place for bore pit area for designated streams S-G26 & S-G27



- Fig. 3 ECD dewatering structure in place for bore pit area for designated streams S-G26 & S-G27



- Fig. 4. At AR 276.03 ECD requires repair.

