

## FIELD INSPECTION

|                                  |                          |                         |                 |
|----------------------------------|--------------------------|-------------------------|-----------------|
| Project Name:                    | Mountain Valley Pipeline | Inspector:              | Marshall Willis |
| Inspection Date:                 | Friday, May 17, 2019     | Project Contact:        | Brian Clauto    |
| Spread I:<br>Pittsylvania County | STA 15826+88 – 15947+64  | Weather (Wet/Dry/Rain): | Wet             |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation  
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Comments: Inspected the following resources: S-G2, W-G2, S-B2, S-H55 and S-H54.

- STA 15848+50 – Maintain P1, re-stabilize stockpile.
- STA 15868+70 – Sediment off ROW, upgrade ECDs.
- STA 15875+00 – Sediment off ROW, re-stabilize upslope areas.

**Recommended Corrective Action:** Maintain and install all controls per the approved plan and specs.

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 05/17/2019

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 17, 2019

Fig. 1: **STA 15826+84** – Controls in place. Area stabilized with Earth Guard.



Fig. 2: **STA 15848+50** – Repair P1, stabilize stockpile.



Fig. 3: **STA 15863+00** – Controls in place. Area stabilized with Earth Guard.



Fig. 4: **STA 15868+70** – Sediment off ROW. Upgrade ECDs/repair as needed.



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 17, 2019

Fig. 5: **STA 15875+00** – Sediment off ROW.



Fig. 6: **STA 15875+00** – Re-stabilize slope.



Fig. 7: **STA 15924+00** – Controls in place.



Fig. 8: **STA 15947+00** – Controls in place.

