

## FIELD INSPECTION

|                                                       |                                                                                  |                                |                 |
|-------------------------------------------------------|----------------------------------------------------------------------------------|--------------------------------|-----------------|
| <b>Project Name:</b>                                  | Mountain Valley Pipeline                                                         | <b>Inspector:</b>              | Marshall Willis |
| <b>Inspection Date:</b>                               | Tuesday, March 26, 2019                                                          | <b>Project Contact:</b>        | Brian Clauto    |
| <b>Spread H:</b><br>Roanoke County<br>Franklin County | STA 13250+00 – 13262+00<br>MVP-FR-291<br>STA 13100+00 – 13156+15<br>STA 12690+00 | <b>Weather (Wet/Dry/Rain):</b> | Dry             |

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- |   |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|---|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?                                                                                                                             | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-II4, S-EF17 and W-EF4.

**Recommended Corrective Action:**

**Deadline:** Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: 03/26/2019

# FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 26, 2019

Fig. 1: **STA 13252+00** – Installation of fabric stabilization with Earth Guard and seed.



Fig. 2: **STA 13117+50** – Area adequately stabilized. Controls in place.



Fig. 3: **STA 13109+78** – Area adequately stabilized. Controls in place.



Fig. 4: **STA 12689+83** – Area adequately stabilized. Controls in place.

