

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 26, 2019	Project Contact:	Brian Clauto
Spread: Roanoke County AR 288 AR 289 MP 246 St12993-13030 MP 240 St12870 Montgomery County AR 279 MP 235 St12453-12451	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments:

- Inspected designated streams and wetlands included: W-KL1, W-Q11, W-IJ10, S-Q20, S-G24, W-ST2PEM. ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- W-IJ10 has had road gravel removed.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 4/9/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 26, 2019

- Fig. 1 W-IJ10 road gravel has been removed



- Fig. 2 St#12451+00 ECD's in place



- Fig. 3 AR279 ECD's in place and functioning



- Fig. 4 Near S-G24 clean water diversion has been installed and functioning

