

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 11, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 13853 – 13888 STA 13575 – 13610	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation
☒ Backfilling and Grade Restoration
 ☒ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|--------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- STA 13863 – STA 13888: Stabilize ROW.
- STA 13879+00: Stabilize stockpiles.
- STA 13576+00: End treatment not installed per project specifications.
- STA 13579: Maintain P1.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 03/11/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 11, 2019

Fig. 1: **STA 13865** – ROW stabilization needed.



Fig. 2: **STA 13870** – ROW stabilization needed.



Fig. 3: **STA 13879+00** – ROW stabilization needed.



Fig. 4: **STA 13876+00** – Stabilization needed on stockpiles.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 11, 2019

Fig. 5: **STA 13879+00** – ROW stabilization needed.



Fig. 6: **STA 13576+00** – Install end treatment per project specifications.



Fig. 7: **STA 13579** – Maintain P1.



Fig. 8: **STA 13590** – ROW at final grade.

