

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, February 14, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County Pittsylvania County	STA 13444 – 13498 STA 15673 STA 15854 - 15879	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☐ Other:

- | | | Yes | No | N/A |
|---|---|--------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Streams / wetlands inspected included: S-IJ10, W-IJ6, S-IJ8, S-B6, W-G2, S-G2, and S-B2.
- CFS undermined at STA 13497.
- CFS full at STA 13497.
- Sediment deposition within wetland W-G2 at STA

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 02/14/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 14, 2019

Fig. 1: **S-IJ10** - Controls in place.



Fig. 2: **STA 13498** - Area stabilized.



Fig. 3: **STA 13497** – CFS undermined. CFS full.



Fig. 4: **STA 13476** – Area stabilized.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 14, 2019

Fig. 5: **STA 13451** – Area stabilized.




Fig. 6: **STA 15673** – ROW-post Earth Guard stabilization.




Fig. 7: **W-G2** – Sediment deposition in wetland at STA 15852+59



Fig. 5: **STA 15858** – ROW-pre Earth Guard application.

