

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, February 14, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP 227 St#12035+19 & 12031+56 MP 228 St#12076+95	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments:

- Inspected designated streams included: S-G36, S-G40, S-G39, and S-MM15. ECD were in place near all the streams, no impacts were observed at the time of the inspection.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 3-1-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, February 14, 2019

- Fig. 1 Area near designated stream S-G36 has been temporarily stabilized and controls are in place.



- Fig. 2 Area near designated stream S-G40 has been temporarily stabilized and controls are in place.



- Fig. 3 Area near designated stream S-G39 has been temporarily stabilized and controls are in place.



- Fig. 4 Area near designated stream S-MM15 has been temporarily stabilized and controls are in place.

