

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, January 23, 2019	Project Contact:	Brian Clauto
Spread: Franklin County MP 277 St#14648-14652 MP276 St#14583-14600 MP261 St#13805-13808 MP265 St#13997-14007 MP254 St#13420-13425 Pittsylvania County MP289 St#15298+34 MP290 St#15355-15358	Spread I	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☒ Pipe Assembly, Testing & Installation

☒ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Stabilization

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |


Comments:

- St#14648-14652 ECD's and stabilization are in place and functioning
- St#14583-14600 ECD's and stabilization are in place and functioning
- St#13805-13808 ECD's and stabilization are in place and functioning
- St#13997-14007 ECD's and stabilization are in place and functioning
- St#13420-13425 ECD's and stabilization are in place and functioning
- St#15298+34 ECD is at capacity
- St#15355-15358 ECD's and stabilization are in place and functioning

Recommended Corrective Action: Maintain all controls per the approved plan and annual standards and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 2-12-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 23, 2019

- Fig. 1 Near station 14652+00 mulch was being applied on 1/23/19



- Fig. 2 Near St#152984+34 ECD is at capacity



- Fig. 3 Near St#13805 stabilization has been applied



- Fig. 4 Near St#13997 stabilization has been applied

