

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, March 31, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	MVP-RO-286 MVP-RO-287 MVP-RO-288 MVP-RO-281	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, March 31, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, March 31, 2021

Figure 1: MVP-RO-286 – Controls in place and functioning properly.
BRG: 291°W (T) LAT: 37.130511 LON: -80.139121 ±25837ft ALT: 2618ft



Figure 2: MVP-RO-286 – Controls in place and functioning properly.
BRG: 275°W (T) LAT: 37.144866 LON: -80.135835 ±16ft ALT: 2684ft



Figure 3: MVP-RO-287 – Controls in place and functioning properly.
BRG: 8°N (T) LAT: 37.134932 LON: -80.137876 ±16ft ALT: 2694ft



Figure 4: MVP-RO-281 – Controls in place and functioning properly.
BRG: 246°SW (T) LAT: 37.182083 LON: -80.145441 ±16ft ALT: 2960ft

