

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 21, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15447+61 – 15630+00	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-CC16, S-CC13, S-CC14, W-CC2-PEM, S-MM8, W-MM5 and S-CC15.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, April 21, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 21, 2021

Figure 1: STA 15478+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard and straw.
BRG: 226°SW (T) LAT: 36.945758 LON: -79.466987 ±11900ft ALT: 895ft



Figure 2: STA 15505+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard and straw.
BRG: 298°NW (T) LAT: 36.905558 LON: -79.472466 ±16ft ALT: 880ft



Figure 3: Stream S-CC14 – Controls in place and functioning properly.
BRG: 288°W (T) LAT: 36.905344 LON: -79.471385 ±16ft ALT: 872ft

