

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, April 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13260+00 – 13342+40 MVP-FR-293.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-II4, S-GH9, S-GH11, S-GH14, S-GH15 and S-GH7.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, April 12, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, April 12, 2021

Figure 1: STA 13305+00 – Controls in place and functioning properly.

BRG: 3°N (T) **LAT:** 37.106920 **LON:** -80.054957 ±8668ft **ALT:** 1379ft



Figure 2: STA 13278+00 – Controls in place and functioning properly.

BRG: 30°NE (T) **LAT:** 37.113848 **LON:** -80.056331 ±16ft **ALT:** 1619ft



Figure 3: STA 13342+00 – Controls in place and functioning properly.

BRG: 296°NW (T) **LAT:** 37.064543 **LON:** -80.053031 ±12113ft **ALT:** 1463ft



Figure 4: STA 13329+00 – Controls in place and functioning properly.

BRG: 329°NW (T) **LAT:** 37.053890 **LON:** -80.056159 ±14160ft **ALT:** 1476ft

